

Important Installation Instructions for Beam Adjuster 16-9916

The gears on these adjusters are made from Powder Metallurgy technology. When welding the base plate to your beam a brazing / copper process must be used in order to achieve proper penetration and strength of the weld.

99-4455-0/0318